

Please replace lines 10-11 on page 5 of the above-captioned application with the following rewritten sentence:

-- The actuator 20 includes [[a]] the housing 26 having a back plate 44 and a cover plate 46. --

Lines ²⁻⁴~~3-5~~ in paragraph [0023] of the published version of the above-captioned application do not correspond with line 33 on page 5 through line 2 on page 6 of the above-captioned application.

CE 2/27/09

Lines ²⁻⁴~~3-5~~ in paragraph [0023] of the published version should read:

CE 2/27/09

-- Through a series of switches, the close command 62 activates the motor [[36]] 30 which rotates to drive the spooling drum 28 to close the closure panel 14. --

Please replace lines 6-9 on page 6 of the above-captioned application with the following rewritten sentence:

-- More specifically, the shaft about which the pinion gear 50 rotates has the rotary power cable 34 fixedly secured thereto such that the rotary power cable 34 rotates equally with the pinion gear [[40]] 50. --